











1 Equipment Curb - Wood
3" = 1'-0"

## Detail Work Description Notes

- 4 NEW STAINLESS STEEL COMPRESSION DRAW BAND
- 5 EXG ROOF PENETRATION TO REMAIN
- EXG METAL DECK TO REMAIN. INSPECT DECK FOR DAMAGE OR DETERIORATION AND REPORT CONDITIONS TO ROOF CONSULTANT

7 NEW IEA-FLEXIBLE SHEET ROOFING (FSR)

- 10 NEW REINFORCED FLEXIBLE SHEET ROOFING MEMBRANE SECUREMENT
- 11 NEW FLEXIBLE SHEET ROOFING SEAM PLATE WITH FASTENERS 12" C/C
- 12 NEW CONTINUOUS MANUFACTURER'S SURFACE MOUNTED TERMINATION
- 13 NEW MANUFACTURERS APPROVED CONTINUOUS TOOLED SEALANT
- 15 EXG METAL EQUIPMENT CURB
- 16 EXG WOOD BLOCKING EQUIPMENT CURB

14 EXG ROOF TOP EQUIPMENT TO REMAIN AT EXISTING HEIGHT

- 19 CLEAN AND PREP SUBSTRATE, PROVIDE NEW FULLY ADHERED FLEXIBLE SHEET ROOFING (FSR) FLASHING
- 20 EXG ROOF DRAIN BOWL TO REMAIN. REPLACE ANY MISSING, BROKEN OR
- 21 NEW CONTINUOUS BEAD OF MANUFACTURER'S WATER CUT OFF MASTIC
- EXG ROOF DRAIN STRAINER TO REMAIN IF MISSING, BROKEN OR PLASTIC REPLACE WITH NEW CAST IRON STRAINER.
- RESET EXG ROOF SUMP CLAMPING RING IN NEW LEAD FLG. REPLACE ANY MISSING AND/OR PLASTIC COMPONENT WITH NEW CAST IRON COMPONENTS. REPLACE EXG PLASTIC STRAINERS WITH NEW CAST IRON
- PROVIDE NEW CAST IRON ROOF OVERFLOW SUMP BOWL, CLAMPING RING, AND STRAINER. SET CLAMPING RING IN NEW LEAD FLASHING
- 25 NEW 20 GA STEEL PLATE MECHANICALLY ATTACHED TO DECK EXTEND 2'-0" MIN. FROM CENTER OF ROOF DRAIN
- BOWL WITH PROPER ATTACHMENT



- NEW MECHANICALLY ATTACHED RIGID INSULATION BOARD AND ADHESIVELY ADHERED COVER BOARD INSULATION
- 2 NEW CONTINUOUS TOOLED LAP SEALANT
- 3 NEW FLEXIBLE PIPE SEAL

- NEW 24 GA PREFINISHED GI SLIP FLASHING MECHANICALLY ATTACHED AT 12" C/C MAX
- 9 REMOVE EXISTING ETHYLENE PROPYLENE DIENE MONOMER ROOFING, INSULATION, SADDLES, FLASHINGS (FLG) CANTS AND STRIPPINGS

- BAR MECHANICALLY ATTACHED 6" C/C MAX. CAULK ALL VERTICAL

- 17 EXG WOOD BLOCKING TO REMAIN. REPLACE ANY DAMAGED OR DETERIORATED WOOD BLOCKING WITH NEW WOOD BLOCKING
- 18 NEW WATER CUT OFF MASTIC
- PLASTIC COMPONENTS WITH NEW CAST IRON COMPONENTS

- 26 CUT DOWN EXISTING OVERFLOW DRAIN PIPE STUB
- 27 INSULATE NEW DRAIN BOWL AND TIE INTO DRAIN LINE AND NEW DRAIN



School Corporation

County



R103

ROOF DETAILS